

CERTIFICATE OF COMPLIANCE

Certificate Number 20150518-EX26635
Report Reference EX26635-20141231
Issue Date 2015-MAY-18

Issued to: SHANGHAI TOP MOTOR CO LTD
303 KANGLIU RD
KANGQIAO INDUSTRIAL AREA
NANHUI
SHANGHAI
201315 CHINA

**This is to certify that
representative samples of** FIRE PUMP MOTORS
Refer addendum page for models

Have been investigated by UL in accordance with the
Standard(s) indicated on this Certificate.

Standard(s) for Safety: UL 1004-1-Rotating Electrical Machines – General
Requirements and UL 1004-5-Fire Pump Motors

Additional Information: See the UL Online Certifications Directory at
www.ul.com/database for additional information

Only those products bearing the UL Certification Mark should be considered as being covered by UL's
Certification and Follow-Up Service.

Look for the UL Certification Mark on the product.



Bruce Mahrenholz, Director North American Certification Program

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please
contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>



CERTIFICATE OF COMPLIANCE

Certificate Number 20150518-EX26635
Report Reference EX26635-20141231
Issue Date 2015-MAY-18

This is to certify that representative samples of the product as specified on this certificate were tested according to the current UL requirements.

T Series, TXD Series, TDC Series, TXA Series, TXD Series:-

T801-2, T802-2, T803-2, T90S-2, T90L1-2, T90L2-2, T100L1-2, T100L2-2, T112M1-2, T112L-2, T132S1-2, T132S2-2, T132M1-2, T132M2-2, T132M3-2, T160M1-2, T160M2-2, T160L1-2, T160L2-2, T180M-2, T180L-2, T200L1-2, T200L2-2, T200L3-2, T225M-2, T225M2-2, T250M1-2, T250M2-2, T280S-2, T280M-2, T280M2-2, T315S-2, T315M-2, T315L1-2, T315L2-2, T355M-2, T355M1-2, T355M2-2, T355L1-2, T355L2-2, T802-4, T803-4, T90S-4, T90L1-4, T90L2-4, T100L1-4, T100L2-4, T100L3-4, T112M-4, T112L-4, T132S-4, T132M-4, T132L1-4, T132L2-4, T160M-4, T160L1-4, , T160L2-4, T180M-4, T180L1-4, T180L2-4, T200L1-4, T200L2-4, T225S-4, T225M-4, T225M2-4, T250M1-4, T250M2-4, T280S-4, T280M-4, T280M2-4, T315S-4, T315M-4, T315L1-4, T315L2-4, T355M1-4, T355M2-4, T355L1-4, T355L2-4, T355L3-4, T803-6, T90S-6, T90L1-6, T90L2-6, T100L1-6, T100L2-6, T112M-6, T112L-6, T132S-6, T132M1-6, T132M2-6, T132L-6, T160M-6, T160L1-6, , T160L2-6, T180L1-6, T180L2-6, T200L1-6, T200L2-6, T200L3-6, T225M1-6, T225M2-6, T250M1-6, T250M2-6, T280S-6, T280M-6, T280M2-6, T315S-6, T315M-6, T315L1-6, T315L2-6, T355M1-6, T355M2-6, T355M3-6, T355L1-6, T355L2-6, TXC143T1U2B, TXC143T1U2B, TXC143T1.5U2B

TXC143T1.5U2B, TXC145T2U2B, TXC145T2U2B, TXC182T3U2B, TXC182T3U2B, TXC184T5U2B, TXC184T5U2B, TXC213T7.5U2B, TXC213T7.5U2B, TXC215T10U2B, TXC215T10U2B, TXC254T15U2B, TXC254T15U2B, TXC256T20U2B, TXC256T20U2B, TXC284TS25U2B, TXC284TS25U2B, TXC286TS30U2B, TXC286TS30U2B, TXC324TS40U2B, TXC324TS40U2B, TXC326TS50U2B, TXC326TS50U2B, TXC364TS60U2B, TXC364TS60U2B, TXC365TS75U2B, TXC365TS75U2B, TXC405TS100U2B, TXC405TS100U2B, TXC444TS125U2B, TXC444TS125U2B, TXC445TS150U2B, TXC445TS150U2B, TXC447TS200U2B, TXC447TS200U2B, TXC449TS250U2B, TXC449TS250U2B, TXC143T1U4B, TXC143T1U4B, TXC145T1.5U4B, TXC145T1.5U4B, TXC145T2U4B, TXC145T2U4B, TXC182T3U4B, TXC182T3U4B, TXC184T5U4B, TXC184T5U4B, TXC213T7.5U4B, TXC213T7.5U4B, TXC215T10U4B, TXC215T10U4B, TXC254T15U4B, TXC254T15U4B, TXC256T20U4B, TXC256T20U4B, TXC284T25U4B, TXC284T25U4B, TXC286T30U4B, TXC286T30U4B, TXC324T40U4B, TXC324T40U4B, TXC326T50U4B, TXC326T50U4B, TXC364T60U4B, TXC364T60U4B, TXC365T75U4B, TXC365T75U4B, TXC405T100U4B, TXC405T100U4B, TXC444T125U4B, TXC444T125U4B, TXC445T150U4B, TXC445T150U4B, TXC447T200U4B, TXC447T200U4B, TXC449T250U4B, TXC449T250U4B, TXC145T1U6B, TXC145T1U6B, TXC182T1.5U6B, TXC182T1.5U6B, TXC184T2U6B, TXC184T2U6B, TXC213T3U6B, TXC213T3U6B, TXC215T5U6B, TXC215T5U6B, TXC254T7.5U6B, TXC254T7.5U6B, TXC256T10U6B, TXC256T10U6B, TXC284T15U6B, TXC284T15U6B, TXC286T20U6B, TXC286T20U6B, TXC324T25U6B, TXC324T25U6B, TXC326T30U6B, TXC326T30U6B, TXC364T40U6B, TXC364T40U6B, TXC365T50U6B, TXC365T50U6B, TXC404T60U6B, TXC404T60U6B, TXC405T75U6B, TXC405T75U6B, TXC444T100U6B, TXC444T100U6B, TXC445T125U6B, TXC445T125U6B, TXC447T150U6B, TXC447T150U6B, TXC449T200U6B, TXC449T200U6B



Bruce Mahrenholz, Director North American Certification Program

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/about/locations/>




CERTIFICATE OF COMPLIANCE

Certificate Number 20150518-EX26635
Report Reference EX26635-20141231
Issue Date 2015-MAY-18

TDC254T15U2B, TDC254T15U2B, TDC256T20U2B, TDC256T20U2B, TDC284TS25U2B, TDC284TS25U2B, TDC286TS30U2B, TDC286TS30U2B, TDC324TS40U2B, TDC324TS40U2B, TDC326TS50U2B, TDC326TS50U2B, TDC364TS60U2B, TDC364TS60U2B, TDC365TS75U2B, TDC365TS75U2B, TDC405TS100U2B, TDC405TS100U2B, TDC444TS125U2B, TDC444TS125U2B, TDC445TS150U2B, TDC445TS150U2B, TDC254T15U4B, TDC254T15U4B, TDC256T20U4B, TDC256T20U4B, TDC284T25U4B, TDC284T25U4B, TDC286T30U4B, TDC286T30U4B, TDC324T40U4B, TDC324T40U4B, TDC326T50U4B, TDC326T50U4B, TDC364T60U4B, TDC364T60U4B, TDC365T75U4B, TDC365T75U4B, TDC405T100U4B, TDC405T100U4B, TDC444T125U4B, TDC444T125U4B, TDC445T150U4B, TDC445T150U4B, TDC254T7.5U6B, TDC254T7.5U6B, TDC256T10U6B, TDC256T10U6B, TDC284T15U6B, TDC284T15U6B, TDC286T20U6B, TDC286T20U6B, TDC324T25U6B, TDC324T25U6B, TDC326T30U6B, TDC326T30U6B, TDC364T40U6B, TDC364T40U6B, TDC365T50U6B, TDC365T50U6B, TDC404T60U6B, TDC404T60U6B, TDC405T75U6B, TDC405T75U6B, TDC444T100U6B, TDC444T100U6B, TDC445T125U6B, TDC445T125U6B

TXA143T1U2B, TXA143T1U2B, TXA143T1.5U2B, TXA143T1.5U2B, TXA145T2U2B, TXA145T2U2B, TXA182T3U2B, TXA182T3U2B, TXA184T5U2B, TXA184T5U2B, TXA213T7.5U2B, TXA213T7.5U2B, TXA215T10U2B, TXA215T10U2B, TXA215T15U2B, TXA215T15U2B, TXA143T1U4B, TXA143T1U4B, TXA145T1.5U4B, TXA145T1.5U4B, TXA145T2U4B, TXA145T2U4B, TXA182T3U4B, TXA182T3U4B, TXA184T5U4B, TXA184T5U4B, TXA213T7.5U4B, TXA213T7.5U4B, TXA215T10U4B, TXA215T10U4B, TXA145T1U6B, TXA145T1U6B, TXA182T1.5U6B, TXA182T1.5U6B, TXA184T2U6B, TXA184T2U6B, TXA213T3U6B, TXA213T3U6B, TXA215T5U6B, TXA215T5U6B

TXD48 1/4U2B, TXD48 1/4U2B, TXD48 1/3U2B, TXD48 1/3U2B, TXD48 1/2U2B, TXD48 1/2U2B, TXD48 3/4U2B, TXD48 3/4U2B, TXD56 1/4U2B, TXD56 1/4U2B, TXD56 1/3U2B, TXD56 1/3U2B, TXD56 1/2U2B, TXD56 1/2U2B, TXD56 3/4U2B, TXD56 3/4U2B, TXD56H 1U2B, TXD56H 1U2B, TXD56H 1.5U2B, TXD56H 1.5U2B, TXD56H 2U2B, TXD56H 2U2B, TXD56H 3U2B, TXD56H 3U2B, TXD143T 1U2B, TXD143T 1U2B, TXD143T 1.5U2B, TXD143T 1.5U2B, TXD145T 2U2B, TXD145T 2U2B, TXD145T 3U2B, TXD145T 3U2B, TXD182T 5U2B, TXD182T 5U2B, TXD184T 7.5U2B, TXD184T 7.5U2B, TXD213T 10U2B, TXD213T 10U2B, TXD215T 15U2B, TXD215T 15U2B, , TXD48 1/4U4B, TXD48 1/4U4B, TXD48 1/3U4B, TXD48 1/3U4B, TXD48 1/2U4B, TXD48 1/2U4B, TXD48 3/4U4B, TXD48 3/4U4B, TXD56 1/4U4B, TXD56 1/4U4B, TXD56 1/3U4B, TXD56 1/3U4B, TXD56 1/2U4B, TXD56 1/2U4B, TXD56 3/4U4B, TXD56 3/4U4B, TXD56H 1U4B, TXD56H 1U4B, TXD56H 1.5U4B, TXD56H 1.5U4B, TXD56H 2U4B, TXD56H 2U4B, TXD143T 1U4B, TXD143T 1U4B, TXD145T 1.5U4B, TXD145T 1.5U4B, TXD145T 2U4B, TXD145T 2U4B, TXD182T 3U4B, TXD182T 3U4B, TXD184T 5U4B, TXD184T 5U4B, TXD213T 7.5U4B, TXD213T 7.5U4B, TXD215T 10U4B, TXD215T 10U4B, TXD56 1/4U6B, TXD56 1/4U6B, TXD56 1/3U6B, TXD56 1/3U6B, TXD56 1/2U6B, TXD56 1/2U6B, TXD56 3/4U6B, TXD56 3/4U6B, TXD56H 1U6B, TXD56H 1U6B, TXD145T 1U6B, TXD145T 1U6B, TXD182T 1.5U6B, TXD182T 1.5U6B, TXD184T 2U6B, TXD184T 2U6B, TXD213T 3U6B, TXD213T 3U6B, TXD215T 5U6B, TXD215T 5U6B, TDC254T15U2B, TDC256T20U2B, TDC284TS25U2B, TDC286TS30U2B, TDC324TS40U2B, TDC326TS50U2B, TDC364TS60U2B, TDC365TS75U2B, TDC405TS100U2B, TDC444TS125U2B, TDC445TS150U2B, TDC447TS200U2B, TDC449TS250U2B, TDC254T15U4B, TDC256T20U4B, TDC284T25U4B, TDC286T30U4B, TDC324T40U4B, TDC326T50U4B, TDC364T60U4B, TDC365T75U4B,



Bruce Mahrenholz, Director North American Certification Program

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>



CERTIFICATE OF COMPLIANCE

Certificate Number 20150518-EX26635
Report Reference EX26635-20141231
Issue Date 2015-MAY-18

TDC405T100U4B, TDC444T125U4B, TDC445T150U4B, TDC447T200U4B, TDC449T250U4B,
TDC254T7.5U6B, TDC256T10U6B, TDC284T15U6B, TDC286T20U6B, TDC324T25U6B,
TDC326T30U6B, TDC364T40U6B, TDC365T50U6B, TDC404T60U6B, TDC405T75U6B,
TDC444T100U6B, TDC445T125U6B, TDC447T150U6B, TDC449T200U6B, TDC504T250U6B



Bruce Mahrenholz, Director North American Certification Program

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>

